



## Service Info



# Tensioner pulley 531 0786 10

## for modified engine tuning

Manufacturer: Ford, Volvo

**Models:**

Ford: Focus II, Kuga I, Mondeo IV, S-Max  
 Volvo: C30, C70 I, C70 II, S40 II, S60 I, S70, S80 I, S80 II, V40, V50, V70 I, V70 II, V70 III, XC70, XC90 I

**Engines:**

Ford: 2.5, 2.5i, 2.5 ST, 2.5 RS  
 Volvo: 2.0, 2.0 T, 2.3 T5, 2.4, 2.4i, 2.4 T5, 2.5 T

**Part no.:**

531 0786 10 (new)  
 531 0787 10 (replaced)  
 530 0467 09 (Set, new)  
 530 0467 10 (KIT, new)  
 530 0467 30 (KIT+Wapu, new)  
 530 0468 09 (Set, replaced)  
 530 0468 10 (KIT, replaced)

For current listing refer to catalog media



Tensioner pulley 531 0787 10

Tensioner pulley 531 0786 10

The engine tuning has been modified for the current series of vehicles listed. This can cause the toothed belt to generate noise at certain engine speeds.

Tensioner pulley 531 0786 10 counteracts those noises and therefore replaces tensioner pulley 531 0787 10.

Tensioner pulley 531 0786 10 is already being installed on the affected engines in current production at the factory. The new part can be retrospectively fitted to earlier vehicles listed

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**  
 Phone: +44 (0) 1432 264 264\*  
 Fax: +44 (0) 1432 375 760  
 hfd-info@schaeffler.com  
 www.schaeffler-aftermarket.co.uk  
 \* Calls from within the UK 08457 001100

Issued 10.2015 INA 0146 Technical content subject to change  
 O.E. Manufacturer's names and numbers are used for reference purposes only  
 © 2015 Schaeffler Automotive Aftermarket GmbH & Co. KG

